



Certificate No: MNDE/REP/0096/01

**Metalock Brazil Ltda
Rua Visconde Do Rio Branco, 20/26
SP 11013-030
Santos
Brazil**

has been approved in accordance with the requirements of Lloyd's Register for the repair of specified components by metal stitching using the 'Metallock' process under the terms of the **Metalock International Association Member Scheme**.

Before any repair is undertaken, Lloyd's Register is to be informed and their agreement obtained.

This approval is subject to compliance with the requirements of Lloyd's Register. Each repair must be undertaken to a written repair procedure that has been accepted by the attending Surveyor. All work is to be completed by fully trained and authorised personnel to the Surveyor's satisfaction.

The metal stitching process cannot be accepted for forgings or castings for pressure vessels, boilers, crankshafts, propellers or other components subject to cyclic loading. The acceptance of any repair as a permanent or temporary means would depend upon the merits of each case.

This Certificate is issued to the above contractor and is valid until the date given below.

Valid until: 22 May 2022
Date of issue: 23 May 2019

Clive Arnold
Senior Metallurgical Specialist to Lloyd's Register EMEA
A member of the Lloyd's Register group